Service Bulletin

FAA-DER APPROVED

Service Bulletin: No. 412-200

Subject:

Removal and Installation - 412AC-300 Air Conditioning System

Compressor Pivot Bolts.

Date:

June 19, 1995

Applicability: Bell Model 412 Helicopters which are equipped with Air Comm

Corporation Cabin Air Conditioning System; serial numbers 33195, 36090

and 36064.

Note: Aircraft serial number 36064 will be upgraded to the ACC drawing

412AC-300 Rev D compressor installation, which will include the changes

listed in this service bulletin.

Reference:

- 1. STC SR00066DE; Bell 412 Air Conditioning System
- 2. ACC drawing ~ 412AC-300 Rev C; Installation Compressor.
- 3. ACC Maintenance Instructions Bell 212/412 Air Conditioning System; Report 412AC-200M.

Background:

It has been determined that the compressor mounting pivot bolt length is too short. Also a bolt torque callout is required.

Mandatory Action Required:

Within twenty-five (25) hours of flight:

Remove and replace the existing Compressor Mount Pivot bolts as shown in figure 1.


Torque the pivot bolt nuts to the specified torque.

Inspect the compressor lugs and compressor mount for evidence of wear, cracks and overall security.

Product Support Procedures:

ACC will provide the following hardware at no charge.

<u>Item</u>	<u>Qty</u>
NAS464-P6LA15 Bolt	2 ea.
AN960-616 Washer	6 ea.
AN960-616L Washer	4 ea.
MS21042L6 Nut	2 ea.



JUL 07 2004