

Service Letter

FAA-DER APPROVED

Service Letter: No. 350

Subject: Alternate compressor drive belt installation for the Bell 412 air conditioner system.

Date: 6 April 2007

Applicability: Bell Helicopter Model 412 CF, Serial Numbers 46400, 46402, 46404, 46406, 46416, 46418, 46428, 46431, 46443, 46447, 46451, & 46475.

Reference: F.A.A./ S.T.C. # SR00066DE, Bell 412 Air Conditioner System Dwg. 412AC-304

Compliance: At the discretion of the operator

Discussion: This alternate compressor drive belt configuration is to allow for the ease of installation and adjustment of the air conditioner drive belts on the Bell Helicopter Model 412 CF only.

Bill of Materials:

Parts to be removed

Item	Part Number	Description	Quantity
1	7320	Belt	1
2	7350	Belt	1


Parts to be installed

Item	Part Number	Description	Quantity
1	7312	Belt	1
2	7355	Belt	1

Weight and Balance:

No adjustment to the weight and balance is necessary for this change.

This area intentionally left blank



View looking inboard from aircraft left, Bell 412 CF